

U.S. Officials Only
SECRETFLD
634

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

COUNTRY Germany (Soviet Zone)

25X1A
REPORT NO. [REDACTED]

SUBJECT Neptun Shipyard

25X1A
PLACE ACQUIRED
(BY SOURCE) [REDACTED]

25X1A

DATE ACQUIRED
(BY SOURCE) [REDACTED]

DATE (OF INFO.) [REDACTED]

RESPONSIVE TO	
1	2
[REDACTED]	

DATE DISTR. 22 Jan 54

NO. OF PAGES 1

NO. OF ENCLS. "

SUPP. TO
REPORT NO.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793 AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE REPRODUCTION OF THIS REPORT IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

25X1X
[REDACTED]

1. In October the Neptun shipyard at Rostock received a 1,000 hp, 620 RPM engine from the Diselmotorenwerk Rostock; also an 800 hp engine for a Soviet ship. A third engine has been delivered for a monopole tug which is to be completed during the last quarter of 1953. However the engines as delivered do not conform to the specifications, due to mistakes in construction. The shaft speed of the engines did not conform to the orifice diameter of 960 mm. An intermediate transmission was put in which adjusted the shaft speed between 360 and 550 RPM, but it turned out that the repair bill was too great at heavy loads. On this account new engines are to be used in the 1954 building program. The Columbus-Propeller-Schmidt firm had undertaken to try to adjust the shaft speed of the six engines on hand, but the results were not satisfactory.
2. The 1954 building program includes four steam tugs, of which two will be built by the Havelberg shipyard and two larger ones by the Neptun yard. It is not yet certain however whether the drifter and seiner program will permit their construction.
3. A Soviet navy tug is at present under repair in the Neptun yard. It has damages to its vacuum pumps, and the entire engine installation is to be provided with auxiliary engines because the radiator heating coils are burned through. No heating coils are available as replacements.
4. A cargo of bolts and ship's plates arrived at Rostock by sea at the end of October. The Neptun yard probably is getting a large Soviet order.

- end -

743.43 4M/C 11/743.416 4M/C(N)
743.41 4M/C 756.134 N(JM)

U.S. Officials Only
SECRET

DISTRIBUTION	STATE	ARMY	NAVY	AIR	FBI				